

ROLLADEN-SCHNEIDER Flugzeugbau GmbH LBA-Nr. EB - 4	Technical Bulletin No. 48	LS1-f	Page 1 / 1
			Edition Jan. 98

Subject : Increase of Service Life

Effectivity : Sailplane LS1, version LS1-f

Accomplishment : Before reaching 3000 hours of service life

Reason : Results of supplementary serviceability tests at main spar booms for wings proved, that service life of GRP-sailplanes may be increased to 6000 hours, if airworthiness of each single sailplane is checked according to a special multiple-stage inspection programme as included into Flight and Maintenance Manual.

Instructions : Pages A and B of Flight and Maintenance Manual entitled "Inspection Sequence to increase Service Life" (Edition Jan. 98) should be entered into Maintenance Manual and recorded in list of pages.

Remarks : This regulation does not affect annual inspections.

Inspections required in chapter "Inspection Sequence to increase Service Life" of Flight and Maintenance Manual should only be carried out at the manufacturer or at an adequately licensed repair shop.

Results of inspections must be recorded in an inspection report, commenting to each inspection step. If inspections are not performed at the manufacturer Rolladen-Schneider, a copy of the report must be sent to him for analysis.

LBA-approved :



13. 09. 99

[Handwritten signature]

Erstellt: 01.Sep.99

[Handwritten signature]

Geprüft:

[Handwritten signature]