

Gegenstand : Fahrwerksantrieb

Betroffen : Segelflugzeugmuster LS6, Baureihe LS6, LS6-a und LS6-b, alle
 Werknummern vor 6151 und WNr.6160

Dringlichkeit : Austausch empfohlen

Vorgang
 Maßnahmen und
 Material : Die im Fahrwerksantrieb eingebaute Gasfeder wird entsprechend
 zugehöriger Arbeitsanleitung durch Teil 4R2-111 ersetzt

Gewicht und
 S.P.-Lagen : vernachlässigbar

Hinweise : Durchführung durch den Hersteller oder durch einen
 anerkannten Luftfahrttechnischen Betrieb.

Bescheinigung der Durchführung durch einen Prüfer Klasse 3 im
 Bordbuch sowie im TM-LTA-Durchführungsbeleg, Wartungshandbuch
 Blatt 14-1.

LBA-anerkannt :



[Handwritten signature]
 -A. F. B. 126

SUBJECT : Landing gear drive

EFFECTIVITY : Sailplane model LS6, versions Ls6, LS6-a and LS6-b, all
 serial numbers before 6151 and S/N 6160.

ACCOMPLISHMENT : Modification recommended

REASON,
 MATERIAL and
 INSTRUCTIONS : Gas strut incorporated in landing gear drive mechanism should
 be exchanged against part No. 4R2-111 according to
 modification instruction

WEIGHT AND
 BALANCE : negligible

REMARKS : Modification by manufacturer or adequately licensed repair
 shop.

Certification of accomplishment by licensed inspector in
 logbook and on TB-AD-Accomplishment List, page 8-1 of
 Instructions for Continued Airworthiness (Maintenance Manual).