

Gegenstand: Flug- und Wartungshandbuch

Betroffen: Segelflugzeug LS3

Dringlichkeit: Bis spätestens 31.3.83

Vorgang: Austausch fehlerhafter Seiten bzw. Ergänzung

Maßnahmen und  
Material: Austausch Blatt 1.3 des Flughandbuchs gegen Ausgabe 1.10.82  
Austausch bzw. Ergänzung der Blätter 3-2, 3-3, 5-1, 12-1 und  
13-12 des Wartungshandbuchs gegen Ausgabe 1.10.82  
Eintrag in die Listen der gültigen Blätter  
Die Fahrtmesser-Farbmarkierung ist zu überprüfen  
und ggf. zu ändern.

Gewicht und  
SP-Lage: Nicht betroffen

Hinweise: Die Seiten können vom Hersteller bezogen werden

Anerkannt vom  
Luftfahrt-Bundesamt *[Signature]*  
- 6. Sep. 1982

Subject: Flight and Maintenance Manual

Effectivity: Sailplane LS3

Accomplishment: Until March 31, 1983

Reason: Exchange of incorrect pages and updating

Instructions: Exchange page 1.3 of Flight Manual against Edition 1.10.82  
Exchange pages 3.3, 5.1, 12.3 and add page 13.12 to  
Maintenance Manual  
Enter in valid pages list

Weight and  
Balance: Not affected

Remarks: Pages may be obtained from manufacturer

LTA 82-215