

Gegenstand: Wölbklappen Rastung
Betrifft: Segelflugzeug LS3
Dringlichkeit: wahlweise
Vorgang: An der linken Bordwand wird eine Rastung für die Wölbklappenstellungen 0° und +5° angebracht.
Maßnahmen und Material: Siehe Zeichnung 3BR-6
Gewicht und SP-Lagen: vernachlässigbar
Hinweise: Die Änderung kann von einer sachkundigen Person durchgeführt werden und muß von einem Prüfer Klasse 3 abgenommen und im Bordbuch bescheinigt werden.
Das erforderliche Material kann nur vom Hersteller bezogen werden.

Subject: Flap Handle Detent
Effectivity: Sailplane LS3
Accomplishment: optional
Reason: A flap handle detent for flap positions 0° and +5° may be fitted to the left fuselage rim.
Instructions and Materials: See Drawing 3BR-6
Weight and Balance: negligible
Remarks: Modification by experienced person. Accomplishment should be checked by inspector and signed in logbook.
Required material may be obtained from the manufacturer.

Anerkannt durch
Luftfahrt-Bundesamt

[Signature]
8. Sep. 1978

Bearbeitet: 4.9.78 *[Signature]*

Geprüft: 4.9.78 *[Signature]*